100

Start

110

COAT EAR SHELL
WITH UV-CURABLE
SUBSTANCE

120

Drain

130

Unload Ear shells from
Platform

140

Place on
carriers

150

UV Post cure

160

Alcohol Rinse

250

UV Cure

260

End

FIG. 1